

# Updated Universal Replacement Furnace Kits


## 21M51U-843 and 21V51U-843 Cover More Two-Stage Applications

July 12, 2016 Bulletin #16-08

Contractors can now service additional Goodman, Lennox, Trane, and York two-stage furnaces with the updated **21M51U-843** and **21V51U-843** kits from White-Rodgers. You can now one-source more 120V HSI applications.

Both kits come with everything needed for a fast and accurate change out. Restores furnace equipment to original factory performance. Also includes Hot Rod™ Universal Ignitor Kit (21D64-2).

**21M51U-843** services more Goodman, Lennox, Trane, and York two-stage furnaces with PSC blower motors and 120V HSI. Kit includes control with Fault Recall and Tri-Color LED display, dipswitches to set blower delays and Hot Rod™ Universal Ignitor. Now replaces additional 16 SKUs for a total of 39 applications.




### 21M51U-843 Cross Reference Replacements:

Goodman	Lennox		Trane/American Standard		White-Rodgers	York International	
20300001	<b>100869-03</b>	83L9301	50M51-495	D341418P02	21M51U-843	<b>67298</b>	<b>S1-03109117000</b>
20300003	18M3401	<b>Y4151</b>	50M61-495	D344301P01	50M61-843	<b>265903</b>	<b>S1-03109168000</b>
50M61-288	<b>39M26</b>		CNT03077	KIT15943		<b>542767</b>	<b>S1-33102954000</b>
50M61-289	46M9901		CNT05122	X13650839010		<b>872670</b>	<b>S1-33103009000</b>
PCBBF120S	50M61-120		CNT6424			<b>50M51-242</b>	<b>S1-33109117000</b>
PCBBF125	<b>63W26</b>		D341418P01			<b>S1-03102954000</b>	<b>S1-33109168000</b>
						<b>S1-03103009000</b>	

**Bold models** are new replacements

**21V51U-843** services more Goodman, Lennox, Trane, and York two-stage furnaces with variable speed blower motors and 120V HSI. Kit includes harness assemblies, control with Fault Recall and Tri-Color LED display, dipswitches to set blower delays and Hot Rod™ Universal Ignitor. Now replaces additional 12 SKUs for a total of 48 applications.



### 21V51U-843 Cross Reference Replacements:

Goodman	Lennox	Thermo Pride	Trane/American Standard		White-Rodgers	York International
20300002	B1809925	<b>100870-01</b>	50V61-143	50V51-507	D341420P02	<b>449572</b>
20300004	B1809927	<b>100870-03</b>		50V61-480	D34142P01	50V51-243
20300006	B1809927S	18M9901		50V61-486	KIT15815	<b>642768</b>
20300006S	PCB00106	<b>19W60</b>		50V61-507	X13650840010	<b>S1-03102955000</b>
50V51-288	PCB00106S	49M5901		CNT03078		<b>S1-03102977000</b>
50V51-289	PCBBF106	50V61-120		CNT04018		<b>S1-33102955000</b>
50V51-290	PCBBF106S	<b>63W27</b>		CNT04352		<b>S1-33102977000</b>
50V61-288	PCBBF107S	<b>Y4152</b>		CNT05120		
50V61-289	<b>PCBBF124S</b>			D156245P01		

**Bold models** are new replacements